

Oil Field Environmental Incident Summary

Incident: 20150603161741 **Date/Time of Notice:** 06/03/2015 16:17

Responsible Party: WHITING OIL AND GAS CORPORATION

Well Operator: WHITING OIL AND GAS CORPORATION

Well Name: P WOOD 154-98-1-27-16-1H

Field Name: TRUAX

Well File #: 28387

Date Incident: 6/2/2015

Time Incident: 13:00

Facility ID Number:

County: WILLIAMS

Twp: 154

Rng: 98

Sec: 27

Qtr:

Location Description:

Submitted By: Sadie Fliegel

Received By:

Contact Person: Sadie Fliegel
1700 BROADWAY STE 2300
DENVER, CO 80290

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 1 Mile

Distance Nearest Water Well: 1 Mile

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	3	Barrels				

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None noted

Areal Extent:

Potential Environmental Impacts:

None noted

Action Taken or Planned:

All standing liquids will be removed and placed back into the tanks. The effected area will pressure washed

Wastes Disposal Location: Oil will be placed back into the tanks

Agencies Involved:

Updates

Date: 6/3/2015 ***Status:*** Reviewed - Assigned to Other Agency

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a valve/piping connection leak, remained on location according to the report. NDIC retains oversight.